

| Report No. | : | 507/2440946 | |
|---------------------------|---|--------------------------------|-------------------|
| Client's Reference | : | Admiralty In Rem No. | : HC/ADM 49/ 2024 |
| | | Warrant of Arrest No. | : HC/WA 17/2024 |
| Instructions | : | 5 th November 2024 | |
| Date of Report | : | 20 th November 2024 | |

5 Tampines Central 1 #03-03 Tampines Plaza 2 Singapore 529541

Tel: +65 6692 6280 (24-hour) Fax: +65 6692 6281 Email: surveys@seawise.com.sg Website: www.seawise.biz

Co. Regn. 53107517J GST Regn. M9-0010070-L

MARIANAS ENVOY

GENERAL CONDITION REPORT

Prepared for:

Sheriff's Office Supreme Court 1 Supreme Court Lane Singapore 178879

Attention: Mr. Mattias Low



This is to certify that at the request of the Sheriff Office, Supreme Court of Singapore, we have attended on board the steel, twin-screw, double hull, tug,

MARIANAS ENVOY

IMO 9118599 of United States of America (USA)

whilst the vessel lay afloat alongside floating berth no. 9, ST Marine Shipyard, Singapore on 11th November 2024 for the purpose of conducting a General Condition and Appraisal of the vessel and have to report as follows:

1. GENERAL PARTICULARS

| Name of vessel | : MARIANAS ENVOY ex KST 34 ex KEJORA EMPAT |
|------------------------|--|
| Call Sign | : Information unavailable |
| Flag/ Port of Registry | : USA/ Guam |
| Owners | : Marianas Tug & Salvage |
| Managers | : Marianas Tug & Salvage |
| Туре | : Tug (3,000 BHP Harbour Tug) |
| Built | : 1995 |
| Builder | : Keppel Singmarine |
| Class | : American Bureau of Shipping ABS |
| Service Speed | : Information unavailable |
| Dimensions: | |
| Length Overall | : 26.33 m |
| Breadth moulded | : 8.51 m |
| Depth moulded | : 4.70 m |
| Draft | : 3.75 m |



Tonnages:

| GT | : 234 |
|---------------------|-------------------------|
| Deadweight | : 107 |
| <u>Capacity</u> : | |
| Cargo | : NA |
| Fuel Oil | : NA |
| Marine Diesel Oil | : Tank reportedly empty |
| Fresh Water Ballast | : Tank reportedly empty |
| Fresh Water | : Tank reportedly empty |
| Lub Oil | : Tank reportedly empty |

Port and Starboard Engines:

2 nos. x NIIGATA model 6L-25 FXD, inline 6-unit, four stroke, medium speed, exhaust gas turbocharged diesel engine with a maximum output of 1,500 PS @ 750 rpm geared to a NIIGATA Z-PELLER ZP-21 CPP azimuth propeller with a maximum continuous output of 1,500 PS @ 306 rpm.

2. SURVEYOR'S NOTE

In this report the following nomenclature is used to describe the condition of items and components:

Good: Condition superior in all respects or better than average, a condition unimpaired original strength and/ or efficiency, no maintenance and or repair is required.

Satisfactory: Condition average, deficiencies of a minor nature not requiring correction: a condition of wear and tear of such an extent as not to affect original strength and/ or efficiency.

Serviceable: Condition below average, condition of wear and tear found to be of such an extent as to reduce strength and/ or efficiency to a degree which does not require immediate corrective measures.



Unsatisfactory: Condition below average, condition of wear and tear found to be of such an extent as to reduce strength and/ or efficiency to a degree which requires immediate corrective measures, or those carrying a period of grace as granted by regulatory bodies.

Poor: Condition deteriorated in all respects, beyond economical repair, requiring renewal or replacement.

3. SURVEY

The vessel was surveyed on 11th November 2024 whilst she lay alongside floating berth no. 9, ST Marine Shipyard, Singapore. At the time of our attendance, she was in afloat condition with approximate drafts of 3.0 m (forward), 3.2 m (mid) and 3.3 m (aft).

The vessel was unmanned and reportedly remained in the shipyard since the time she entered for dry-docking in 21st May 2021. An extensive array of docking works was carried out by the shipyard prior to her lay-up. The vessel was officially laid up by her Classification Society, ABS, since August 2023 to present.

4. HULL EXTERNAL PLATING

Port and starboard shell plating from bulwark to waterline level were noted in good condition and free of contact damage. Transom plating was found in good condition observed from the main deck (aft). Both propeller and rudder were completely submerged and could not been viewed.

Hull plating paintwork on port and starboard sides was noted to be in good condition. It was noted that the vessel underwent drydocking in ST Marine Shipyard on 21st May 2021 and amongst the jobs carried out were hull blasting, painting and bulwark renewals.

5. MAIN DECK (FWD)

The forecastle deck bulwark plating with connecting stays, air pipes, forward towing staple, pedestal fairleads etc. were all noted to be intact, in good condition and well coated.

She is also fitted with 1 no. double gypsy, single drum windlass/winch connected to warping heads on each side but without any mooring ropes in the drum. The winch was well re-rusted and well coated.



The forward deck plating was in good condition and also well painted.

The main deck underwent grit blasting and painting in the yard in 2021.

6. FORWARD STORE

The forward store or rope store space appeared to be in satisfactory condition and free of any structural damage. Weathertight door was in good condition.

7. MAIN DECK (AFT)

The vessel is fitted with 1 nos. BODEWES electro-hydraulic mooring hawser/ towing winch warping heads, connecting stays, air pipes, were noted in good condition. Winch was found without any mooring rope. Towing staple was found in good condition. Skylight openings for port and starboard azimuth propellers were located on the main deck (aft).

8. ACCOMMODATION SPACES

The accommodation casing, including all surrounding external decks, walkways and fittings, were intact and well coated. The accommodation space was designed only on the main deck floor.

The vessel has 3 air-conditioned cabins sufficient for a maximum of 8 persons.

This space also includes a kitchenette and dining area on the same floor. The kitchenette included an electric stove top, exhaust hood and a sink with stainless steel countertop and storage and was in satisfactory condition. The space also includes a refrigerator and chest freezer.

An access ladder connects the accommodation space to the wheelhouse through a hatch.

9. SAFETY EQUIPMENT

The vessel is fitted with the following life-saving appliances:

- 1) 2 nos. liferaft (8-person each)
- 2) 12 nos. life jacket
- 3) 2 nos. Lifebuoy with light and smoke
- 4) 2 nos. lifebuoy with light
- 5) 2 nos. lifebuoy with line

5



- 6) 2 nos. Lifebuoy
- 7) 1 no. first aid kit
- 8) 1 set of 12 nos. rocket parachute
- 9) 3 nos. portable 2-way radio
- 10) 1 nos. EPIRB
- 11) 2 nos. Embarkation ladder (rope)

The vessel is fitted with the following fire-fighting equipment:

- 1) 3 nos. Fire Control Plan
- 2) 1 no. Bilge pump
- 3) 1 nos. Fire and general service pump
- 4) 1 nos. diesel driven Portable Emergency fire pump (not sighted)
- 5) 4 nos. hose box with spray nozzles
- 6) 4 nos. fire hydrant
- 7) 4 nos. Portable foam fire extinguisher
- 8) 6 nos. Portable CO2 fire extinguisher
- 9) 1 no. Portable water fire extinguisher
- 10) 1 no. Portable dry powder fire extinguisher
- 11) 1 no. wheeled fire extinguisher (45L)
- 12) 1 nos. BA set

All of the equipment servicing were **OVERDUE** and last inspected in 2020.



10. WHEELHOUSE EQUIPMENT

The navigation bridge / wheelhouse space is fitted with the following equipment:

| No. | DESCRIPTION | MANUFACTURER | MODEL | QTTY | LAST SERVICE |
|-----|-----------------------|--------------|-----------|------|-------------------------|
| 1 | Watch Alarm | SM electrics | | 1 | Information unavailable |
| 2 | VHF | SANYONG | STR 6000A | 1 | Information unavailable |
| 3 | PA system | SHOW | SA-25 | 1 | Information unavailable |
| 4 | Window wiper controls | | | 1 | Information unavailable |
| 5 | VHF radio | ю | IC-M424 | 1 | Information unavailable |
| 6 | Autopilot | Tokimec | PR-2000 | 1 | Information unavailable |
| 7 | Radar | FURUNO | 1715 | 1 | Information unavailable |
| 8 | Echo sounder | FURUNO | | 1 | Information unavailable |
| 9 | Navtex | JMC | NT-1800 | | Information unavailable |
| 10 | Portable radio | Samyung | | 3 | Information unavailable |

Main Engine:

2 nos. x NIIGATA model 6L-25 FXD, inline 6-unit, four stroke, medium speed, exhaust gas turbocharged diesel engine with a maximum output of 1,500 PS @ 750 rpm geared to a NIIGATA Z-PELLER ZP-21 CPP azimuth propeller with a maximum continuous output of 1,500 PS @ 306 rpm.

The main engine was found covered with tarpaulin material. The shipyard did not carry out any works to both engines. Maintenance records from the vessel were not available onboard.

Sump oil renewal and equipment servicing will be required due to prolonged laid up status.

Port engine running hour meter revealed 61,192 total running hours. This could not be verified with any existing maintenance records.

Starboard engine running hour meter appeared faulty.



Diesel Generators:

Aux. Engine nos. 1 and 2:

2 nos. Detroit diesel engines coupled to synchronous generators rated at 80 kW, 380 V, 3 phase, 50 Hz, 0.8 power factor.

Aux engine no.1 (forward) running hours: Information unavailable

Aux engine no. 2 (aft) running hours: Information unavailable

Maintenance records for auxiliary engines were unavailable on board.

Sump oil renewal and equipment servicing will be required due to prolonged laid up status.

Air Compressors

2 nos. electric main air compressors appeared to be in satisfactory working condition. Compressor oil renewal and equipment servicing will be required due to prolonged laid up status.

Main & Auxiliary Cooling Pumps

Main and auxiliary engines cooling pumps were all noted in satisfactory condition.

Steering Gear

She is fitted with 2 nos. NIIGATA Z-PELLER ZP-21 CPP azimuth propeller with a maximum continuous output of 1,500 PS @ 306 rpm each.

Silent Room (Switchboard room)

Silent room has the following fittings:

- Main switchboard and distribution boards.
- Aux. engine synchronising panels
- Main engine alarm panels

All of the above equipment were not powered due to laid up status.



Machinery Space

The machinery space requires housekeeping.

11. SPEED AND CONSUMPTION

Information unavailable

12. SURVEY STATUS AND NOTATIONS

The vessel was classed with **ABS** rules with the following notation:

A.B.S. + A1 E + AMS "Towing Services"

No certificates were available onboard.

The vessel officially received her laid up status from class in August 2023.

13. TRADING CERTIFICATES

No certificates were available onboard for our review.

14. GENERAL COMMENTS

The vessel was found in satisfactory condition except for the following:

- 1. Port and Starboard engines will require engine pre-starting checks and lubricating oil sump renewals due to prolonged laid up status.
- 2. Auxiliary engines Port and Starboard engines will require engine pre-starting checks and lubricating oil sump renewals due to prolonged laid up status.
- 3. Engine room, accommodation and wheelhouse will require housekeeping.
- FIFI pump engine will require engine pre-starting checks and lubricating oil sump renewals due to prolonged laid up status. FIFI pump will require servicing due to corrosion found in way of pump casing.
- 5. Control and Instrumentation equipment such as alarms, remote monitoring systems etc. will require checks.



- 6. Hydraulic oils from winch reservoir and Z-peller storage tanks will need to be analysed before use due to prolonged laid up status.
- Auxiliary engine nos. 1 and 2 major overhauls are reported as overdue however no running hour records were available on board.
- 8. All LSA and FFE will require servicing and/or replacement.
- 9. Vessel will need to be reclassified under her existing Classification Society and recertified accordingly before trading.
- 10. Vessel was reported by the yard to be *without any DO and LO bunkers*.
- 11. During vessel's time in the shipyard in 2021, the following works were carried out:
 - a. The dry-docking jobs that were carried out include external hull blasting and painting, renewal of anodes and fenders, servicing and renewal of sea valves, and renewal of column seals on the Z-peller azimuth propellers (port and starboard) and renewal of shell plates.
 - For steel work, various deck, accommodation, and bulwark plates were renewed, and numerous hull outfitting jobs were performed throughout the vessel. Additionally, pressure testing of tanks were carried out.
 - c. The electrical and general fitting aspects of the repair scope consists of servicing of electrical motors, replacement of lights, troubleshooting of various electrical issues, removal and reinstallation of cables to facilitate steel renewal access works, refurbishment of accommodation toilets and access works in the accommodation, mess room, air-conditioning room, engine control room and engine room.
 - d. Range of pipes including seawater, fresh water, fuel oil, vent, sounding, ballast, hydraulic, exhaust, grey/black water, fire lines, drain, and lube oil systems were also renewed.
 - e. Mechanical jobs included servicing of heat exchangers, pumps, and intermediate valves, as well as the installation of new pumps and servicing of deck equipment such as winches and hydraulic motors.



f. The main deck underwent grit blasting and painting, while most of the superstructure and exposed structures were power tooled and painted. Furthermore, the engine room and steering gear bilges were cleaned, and most of the tanks were cleaned in preparation for survey inspections.


15. PHOTOGRAPHS


Photographs taken in the form of digital images, recorded during our attendance, are attached to and form part of this report. The undersigned confirms that the images reproduced here are a fair and reasonable representation of our findings at the time of our attendance.


MALIM ARAFFIZ Divisional Director


16. ENCLOSURES


| Fire control plan | Х |
|------------------------------|---|
| Photographs | Х |
| SEAWISE terms and conditions | Х |












| | | | | LOCA | ATION | 1 | | | | |
|-----------------------|--------|--|-------------|--------|--------------|-------|--|-------|----------------|---|
| Y PLAN | SYMBOL | DESCRIPTION | BRIDGE DECK | I DECK | DW MAIN DECK | | REMARKS | | SYMBOL | DESCRIPTIO |
| Statement of the | | LIFE SAVING APPLIANCES | NAV. | MAIN | BELOW | TOTAL | | A. S. | and the second | PINE BACK AND AND |
| : | 0 | LIFERAFT Rakit keselamatan | 2 | | | 2 | 8 NEN EACH C/W Hydrostatig Reltase | - | | FIRE CONTROL PLAN PELAN KAWALAN KEBAKARAN |
| and the second second | R | UFEJACKET JAKET KESELAMATAN | 2 | 8 | 2 | 12 | WITH WHISTLE AND REFLECTION TAPE | 1 | | BILGE PUMP PAM BILGA |
| and the second | 0 | LIFE BUOY WITH LIGHT AND SMOKE BOYA KESELAMATAN DENGAN ISYARAT LAMPU DAN ASAP | 2 | | | 2 | with self-ignited Light | 1 | | FIRE AND GENERAL SERVICE PU PAM BOMBA DAN G.S. |
| ST LEAN | 0 | LIFE BUOY WITH LIGHT BOYA KESELAMATAN DENGAN ISYARAT LAMPU | | 2 | | 2 | with self-ignited Light | | | PORTABLE EMERGENCY FIRE PU |
| | 0 | LIFE BUDY WITH LINE BOYA KESELAMATAN DENGAN TALI KESELAMATAN | | 2 | | 2 | WITH 27.5M BUOYANT Line | | | FUEL OIL PUMP REMOTE SHUT- Kawalan Penutupan Pam Bahy |
| | 0 | UFE BUOY BOYA KESELAMATAN | | 2 | | 2 | 5 -4' | | | REMOTE CONTROL FOR FUEL OF |
| | Ð | FIRST AID KIT | | 1 | | 1 | | | | HOSE BOX WITH SPRAY/JET NO HOS BOMBA DENGAN MUNCUNG |
| | | LINE THROWING APPLIANCE | 1 | | | 1 | 1 SET CONSIST 4 LINES EACH LINE NOT LESS THAN 230M & 2 PROJECTILES | | | FIRE HYDRANT (#38mm) PILI BOMBA (#38mm) |
| | | ROCKET PARACHUTE FLARES | 1 | | | | SET OF 12 IN CLEARLY MARKED WATERTIGHT CASE | | | FIRE BUCKET C/W 3M LANYARD BALDI KEBAKARAN DENGAN 3M |
| | | PORTABLE 2-WAY VHF RADIO RADIO VHF 2 HALA PORTABLE | - 3 | | | 3 | | | 8 | FIRE ADE |
| | | | 1 | Π | | 1 | | | 20 | LOCKER WITH FIREMAN'S OUTFIT |
| | 1 | EMBARKATION LADDER (ROPE) | | 2 | | 2 | | | E. | PORTABLE FOAN FIKE EXTINGUIS ALAT PEMADAN API BUSA BINDI |
| | 豪 | LIFERAFT EMBARIKATION LIGHT (60W 24V DC) | 2 | Π | | 2 | | | | PORTABLE CO2 FIRE EXTINGUISH ALAT PEMADAM API CO2 BIMBIT |
| | F | PRIMARY ESCAPE ROUTE | - | | | | | . [| | PORTABLE WATER FIRE EXTINGUE ALAT PEMADAM API AIR BINBIT (|
| | TH | RUDAR THANSPONDER (SART) | 2 | | 2 | 2 | | | | PORTABLE DRY POWDER FIRE ED ALAT PEMADAM API TEPUNG KER |
| IV I | Prost. | TRUNSPONDER RADAR (SAET) | | | | | | | | WHEELED FIRE EXTINGUISHER ALAT PEMADAM API BERODA |
| <u> </u> | C | 1 | | | | | | | | BREATHING APPARATUS RADAS PERNAFASAN |

| | | REMARKS | SYMBOL | DESCRIPTION | . BRIDGE DECK | MAIN DECK | OW MAIN DECK | AL | REMARKS |
|--------|-------|---|--------|---|---------------|-----------|--------------|-----------|--|
| | TOTAL | | | FIRE FIGHTING EQUIPMENT | NAV. | MAIN | BELOW | TOTAL | |
| 13 | 2 | 8 WEN EACH C/W HYDROSTATIC RELEASE | | FIRE CONTROL PLAN PELAN KAWALAN KEBAKARAN | | 3 | | 3 | 2 AT MAIN DECK EXTERNAL TO BE KEPT IN MALER TIGHT CONTAINER (PAIS) |
| | 12 | WITH WHISTLE AND REFLECTION TAPE | | BILGE PUMP | | | 1 | 1 | SO CULL/HR @ 35M HEAD |
| | 2 | WITH SELF-KONITED | | FIRE AND GENERAL SERVICE PUMP PAN BOMBA DAN G.S. | | 1 | 1 | 1 | 60 CULL/HR @ 35M HEAD |
| | 2 | WITH SELF-KONITED | | PORTABLE EMERGENCY FIRE PUMP PAM KECEMASAN BOMBA | | 1 | | 1 | DIESEL DRIVEN SIZE NO. 7 |
| | 2 | WITH 27.5M BUOYANT | | FUEL OIL PUMP REMOTE SHUT-OFF KANALAN PENUTUPAN PAM BAHAN API | | 1 | | 1 | |
| 1 | 2 | -4' | | REMOTE CONTROL FOR FUEL OIL VALVES | | 1 | | 1 | |
| - | 1 | | | HOSE BOX WITH SPRAY/JET NOZZLE HOS BOMBA DENGAN MUNCUNG JET/SEMBUR | | 2 | 2 | 4 | WITH 438mm HOSE MAN DECX - 15W EVGINE ROOM - 10W |
| | 1 | 1 SET CONSIST 4 LINES EACH LINE NOT LESS THAN 230M & 2 PROJECTLES | | FIRE HYDRANT (#38mm) | | 2 | 2 | 4 | |
| | 1 | SET OF 12 IN CLEARLY WARKED WATERTIGHT CASE | . 🗑 | FIRE BUCKET C/W 3M LAWYARD BALDI KEBAKARAN DENGAN 3M TALI KURANG 1 NOS. | | 1 | 2 | 3 | BUCKET TO BE PAINTED RED WITH 'FIRE'. WORDING |
| 2 | 3 | | 8 | FIRE ADE | | 1. | | 1 | WITH INSULATED HANDLE |
| | 1 | | | LOCKER WITH FIREMAN'S OUTFIT | | 1 | | 1 | SEE NOTE 1 |
| | 2 | | | PORTABLE FOAM FIRE EXTINGUISHER (91.) ALAT PEMADAM API BUSA BIMBIT (91.) | 1 | 2 | 2 | 4 | SPARE CHARGES OTY. 4 |
| 6 | 2 | | | PORTABLE CO2 FIRE EXTINGUISHER (6.8 KG) | 1 | 1 | 4 | 6 | SPARE CHARGES CITY. 6 |
| 1 | - | | E | PORTABLE WATER FIRE EXTINGUISHER (9L) | | 1 | | 1 | SPARE CHARGES OTY. 1 |
| 1 | é | and the second as | | PORTABLE DRY PONDER FIRE EXTINGUISHER (6 KG) ALAT PEMADAM API TEPUNG KERING BINBIT (6 KG) | | 1 | | 1 | SPARE CHARGES GTY. 1 |
| - | | Real Property | THE . | WEELED FIRE DATINGUISHER | | | 1 | 1 | FONM - 45 LITRES |
| | - | | | BREATHING APPARATUS | | 1 | | 1 | C/W 2 SPARE BOTTLES |
| | | | E | INTERNATIONAL SHORE CONNECTION | | 1 | | 1 | |
| | | | | EMERGENCY TELEPHONE STATION | 1 | 1 | 1 | 3 | BATTERY OPERATED |
| | | | | STESEN TALIPON KECEMISAN SNOKE DETECTOR | 1 | 1 | 1 | 3 | |
| RETARD | WIT E | KOARD | | PENGESAN ASAP SNOKE DETECTOR (WATERTIGHT) | | | | 4 | |
| | | | | PENCESAN ASAP (WATERTIGHT) Heat detector | | 1 | | 3 | |
| - | | | | PENCESANI HABA MANUALLY OPERATED CALL POINT | - | - | 7 | | and a second second second |
| | | - | | PUSAT PANGGLAN WANUL BELL FIRE ALARM LOCENG FENGGERA KEBAGAWA | 1 | 1 | 1 | 3 | |
| | | | | BELL FIRE ALARM (WATERTICHT) | | | 3 | 3 | |
| | | | | Locens Pensgera Kednavan (naterticht) Fire Alarm Rotating Licht (RED) Lawpu (Mernh) Amarini Api | | | 1 | 1 | |
| 0 | 7 | 1 | | SPENCE | 1 | 1 | | 2 | |
| VENT | | | | SPEAVER WITH TALK BACK SYSTEM | | 2 | | 2 | |
| 1: | | | | PUSH BUTTON FOR GENERAL ALARM | 1. | | | 1 | |
| AF. | 2 | 1.1.1.1.1.1.1 | | LUBE OIL PUMP REMOTE SHIT-OFF | 1, | 1 | | 2 | |
| - | - | e | | KAWALAN PENJUPAN PAM CU | 1. | 1 | | 2 | |
| K | * | | | KIPAS PENGINAPAN DAN PENGHAWA DIKON RENOTE FIRE DAMPER FOR ACCOMMODATION VENTLATION | F | 1 | | 1 | |
| 1: | Í | THR- | | FEMAWA/PENUTUP API UNTUK PENGAWPAN FIRE DAMPER FOR ENGINE ROOM VENTLATION | - | 1 | - | | |
| 10 | 1 | | | PENNINN/PENUTUP API UNTUK ENGINE ROOM Closing device for ventlation inlet or outlet | . | + | - | <u>'</u> | |
| 0 | | . 18 | | PENJUP UNTUK PENCUDARAN MASUK/KELLAR CLOSING DEVICE FOR VENTLATION INLET OR OUTLET | 1 | - | - | <u> '</u> | ACCOMMODATION SPACE |
| | | | | PENJTUP UNTUK PENGUDARAAN WASUK/KELLAR | | • | - | • | WOIDERY SPICE |
| | | | | LOCENIS | | ' | - | 1 | |
| | | 3 (| | | 1 | - | | | |
| | - | | | 1 | | | | | |

•



NAV. BRIDGE DECK

PRINCIPAL PARTICULARS


| LENGTH O.A. | 26.33 M |
|---------------------------------------|-----------------|
| BREADTH MLD. | 8.51 M |
| DEPTH MLD. | 4.70 M |
| DESIGNED DRAFT | 3.75 M |
| COMPLEMENT | 8 MEN |
| GROSS TONNAGE | 234 TONS |
| ENGINE PARTICULAR | NIIGATA 6L25HLX |
| TRADE LIMIT | NEAR COASTAL |
| SHIP NAME | KEJORA EMPAT |
| PORT OF REGISTRY | PORT KELANG |
| · · · · · · · · · · · · · · · · · · · | |



JABATAN LAUT (MARINE DEPART Unit (S D I L seperti (A I as a (A Tarikh 10.07. Tarikh 10.07. Tarikh 10.07. Tarikh 10.07.

DECK

. .





001. Attended on board MARIANAS ENVOY on 11th November 2024 whilst she lay afloat secured to Berth 9 at ST Marine Shipyard, Singapore.



002. Portside view of the vessel.



003. Plimsoll mark and hull general coating appeared in good condition.



004. Forward fenders replaced.



005. Aft fenders replaced.



006. View of superstructure and wheelhouse.

Our Ref.: 507/2440946



007. Fore-end of the vessel with towing staple well coated.



008. Forward fenders.



009. Towing staple and forward fenders.



010. Winch and windlass.


Our Ref.: 507/2440946



011. Portside main deck.



012. Starboard side main deck.



013. Portside chain in satisfactory condition.



014. Forward store.

Our Ref.: 507/2440946



015. Forward store.




016. Forward winch and windlass brakes.

Our Ref.: 507/2440946



017. Close up view of new brake pads.



018. Engine room vent.




019. Starboard accessway on main deck.



020. Main deck (aft).



021. Z peller compartment exhaust vent.



022. Good deck plating condition.



023. Two anchors laid on the main deck (aft).



024. Towing winch (aft).



025. Brake pads in satisfactory condition.



026. Rope drum.


Our Ref.: 507/2440946



027. Towing winch nameplate.



028. Towing staple.



029. Portside main deck accessway.



030. Navigation bridge deck.



031. Life raft 10 person capacity.



032. Top view of main deck (aft).



033. Fire control plan on navigation bridge deck.



034. Wheelhouse.



035. Access hatch into crew accommodation space.



036. Wheelhouse ceiling panels in good condition.



037. Wheelhouse control console.



038. VHF radio.

Our Ref.: 507/2440946



039. PA system.



040. Window wipers.



041. Lighting switches.



042. Steering console.



043. Wheelhouse console namplate.



044. Vessel alarm panel.



045. Autopilot system.



046. Port and starboard propeller controls.

Our Ref.: 507/2440946



047. Radar.




048. Echo sounder.

Our Ref.: 507/2440946



049. Navtex receiver.



050. Engine clutch controls.



051. Ditto.



052. Hawser winch control panel.

Our Ref.: 507/2440946



053. Lighting panel.



054. 3 nos. GMDSS radios.



055. Aft facing steering and winch control console.



056. Console nameplate.

Our Ref.: 507/2440946



057. Console lower controls.



058. LSA and FFE found expired.



059. Access hatch ladder into accommodation.



060. 2-man cabin.

Our Ref.: 507/2440946



061. Ditto.



062. 2-man cabin.

Our Ref.: 507/2440946



063. Crew quarters common space.



064. Kitchenette.

Our Ref.: 507/2440946



065. Dining corner.



066. Remote VHF handsets.

Our Ref.: 507/2440946



067. 4-man cabin.



068. Toilet entrance.



069. Laundry corner with washer and dryer.



070. Seperate toilet and shower cubicles.



071. Spiral stairs into engine room.



072. Tool bench and storage area in engine room.

Our Ref.: 507/2440946



073. Ditto.



074. Air bottles.

Our Ref.: 507/2440946



075. Starboard engine cooler.



076. Starboard engine cooler.

Our Ref.: 507/2440946



077. Hydraulic power pack.



078. Replaced sw overboard piping.



079. Overboard valves appeared newly replaced.



080. Hydraulic power pack.

Our Ref.: 507/2440946



081. Fuel service tanks.



082. Newly installed pump and motor, likely for seawater system.

Our Ref.: 507/2440946



083. Starboard engine.



084. 2 nos. auxiliary engines.

Our Ref.: 507/2440946



085. Portside engine.



086. Main engine lubricating oil service tank.



087. Portside main engine cooler.



088. Portside main engine cooler.



089. Some replaced piping.



090. Portside of engine room.



091. 2 nos. fuel transfer pumps.



092. Fuel transfer pump control panels.

Our Ref.: 507/2440946




093. Engine driven FIFI pump.



094. Corrosion found in way of pump casing.



095. Corrosion in way of FIFI pump outlet valve.



096. FIFI pump inlet piping with strainer.



097. Exhaust insulation covers appeared new.



098. Generator engine switchboard.



099. Generator engine switchboard.



100. Silent room.



101. Main engine alarm and indicator panel.



102. Main engine alarm and indicator panel.



103. Steering room, portside azimuth transmission and hydraulic pipings.



104. Skylight.

Our Ref.: 507/2440946



105. Nameplate.



106. Steering room, starboard azimuth transmission and hydraulic pipings.

Our Ref.: 507/2440946



107. Skylight.



108. Nameplate.

Our Ref.: 507/2440946



109. Input shaft from engine.



110. Hydraulic storage tanks in steering gear room.

Our Ref.: 507/2440946



111. Main mast.



112. Monkey island.



113. 2 sets emergency battery bank.



114. FIFI water monitor.



SEAWISE Maritime Services

5 Tampines Central 1 #03-03 Tampines Plaza 2 Singapore 529541

Tel: +65 6692 6280 (24-hour) Fax: +65 6692 6281 Email: surveys@seawise.com.sg Website: www.seawise.biz

Co. Regn. 53107517J GST Regn. M9-0010070-L

ANNEX 1

SEAWISE Maritime Services (SMS) - Terms and Conditions

In providing services, information or advice neither SEAWISE Maritime Services (SMS) nor any of its officers, employees or agents warrants the accuracy of any information or advice supplied. Except as set out herein, neither SMS nor any of its officers, employees or agents (on behalf of each of whom SMS has agreed this clause) shall be liable for any loss, damage or expense whatever sustained by any person due to any act, omission or error of whatsoever nature and howsoever caused of SMS, its officers, employees or agents or due to any inaccuracy of whatsoever nature and howsoever caused in any information or advice given in any way whatsoever by or on behalf of SMS, even if held to amount to a breach of warranty.

Nevertheless, if any person, who is party to the agreement pursuant to which SMS provides any service, uses SMS's services or relies on any information or advice given by or on behalf of SMS and suffers loss, damage or expense thereby which is proved to have been due to any negligent act, omission or error of SMS, its officers, employees or agents or any negligent inaccuracy in information or advice given by or on behalf of SMS, then SMS will pay compensation to such person for his proved loss up to but not exceeding the amount of the fee (if any) charged by SMS for that particular service, information or advice.

SMS, its officers, employees or agents (on behalf of each of whom this notice is given) shall be under no liability or responsibility in negligence or otherwise howsoever to any person who is not a party to the agreement with SMS pursuant to which any certificate, statement, data or report is issued in respect of any information or advice expressly or impliedly given by SMS or in respect of any omission or inaccuracy therein or in respect of any act or omission which has caused or contributed to any certificate, statement, data or report being issued with the information and advice it contains (if any).

The services provided by SMS do not include any checks or tests whatsoever to establish whether any computer hardware and/or software, embedded microchips or data storage or information technology equipment or system is capable of handling changes in date and/or time data or information without loss of performance or functionality, unless otherwise stated expressly in writing by SMS. Any dispute concerning the provision of SMS's services and/or the contract under which such services are provided is subject to the exclusive jurisdiction of the England courts and will be governed by England law.